

| Site Name | Feature Location | 6 D's | Reasons | Existing species | Planting notes | Replant species |
|-------------------|------------------|-----------|---------------------------------------------------------------|------------------|------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------|
| BIRLEY MOOR CLOSE | o/s 5 | Dangerous | Laetiporus sulphureus infection | Prunus Kanzan | Outside 5 in tree pit. | TR: Replanting- Malus 'Rudolph' - Outside 5 in tree pit. |
| BIRLEY MOOR CLOSE | s/o 4 - facing 9 | Damaging | Kerbstone displaced by root pushing on kerb rear | Prunus Kanzan | Plant in new 800mm pit at s/o 4 (facing 9) (same as felled tree) | TR: Replanting, Malus 'Rudolph' - Plant in new 800mm pit at s/o 4 (facing 9) (same as felled tree) |
| BIRLEY MOOR CLOSE | o/s 2 | Damaging | Rooting above tarmac in f/w, will be damaged upon planing off | Prunus Kanzan | 1 ' | TR: Replanting, Malus 'Rudolph' - Plant in new 800mm pit at o/s 2 (same as felled tree) |
| BIRLEY MOOR CLOSE | o/s 1 | Dangerous | Structural integrity -weak union @ crown break | Prunus Kanzan | , , | TR: Replanting-Sorbus aucuparia 'Cardinal' o/s 1 in original tree pit. |
| BIRLEY MOOR CLOSE | o/s 3 | Dangerous | weak union at crown break- Structural Integrity - | Prunus Kanzan | o/s 3 | TR: Replanting-Prunus 'Umineko' - o/s 3 close to 5 in original location in tree pit. |
| BIRLEY MOOR CLOSE | o/s 7 | Damaging | significant root damage to the footway | Prunus Kanzan | | TR: Replanting- Sorbus aucuparia 'Cardinal' - o/s 7 in original tree pit. |